Uttley Croft
Vicarage
Church
Basford Close
O/S 77
Post
Basford Drive
Basford Mews
Harney Close
Darnall Drive
Post
Builder's
O/S 74
Basford Street
Industry Road
Darnall Ro
Ball Inn
DARNALL
Surgery
Markaz
Existing Trees for Removal
O/S - Outside Property Number
© Crown copyright and database rights 2015 Ordnance Survey 100018816
Scale: 1:913
N

Site Name	Feature Location	6 D's	Reasons	Existing species	Planting notes	Replant species
BASFORD STREET	o/s 74	Damaging	Substantial root in f/w above tarmac, cannot work around without damage	Prunus serrulata	o/s 74 in original location in verge	TR: Replanting- Crataegus 'Pauls Scarlett'
BASFORD STREET	o/s 77	Dangerous	Substantial stem decay, extremely poor condition	Sorbus aucuparia sp	o/s 77 in original location in verge	TR: Replanting- Crataegus 'Pauls Scarlett'